$$DF = \frac{WCO2 - WCO2_d}{WCO2_e - WCO2_d} - 1$$

(c) Humidity calculations. (1) The following abbreviations (and units) apply to paragraph (b) of this section: BARO=barometric pressure (Pa). H=specific humidity, (g H₂O/g of dry air). K_H=conversion factor=0.6220 g H₂O/g dry air. M_{air}=Molecular weight of air=28.9645. M_{H2O}=Molecular weight of water=18.01534. P_{DB}=Saturation vapor pressure of water at the dry bulb temperature (Pa).

P_{DP}=Saturation vapor pressure of water at the dewpoint temperature (Pa).

P_v=Partial pressure of water vapor (Pa).
 P_{WB}=Saturation vapor pressure of water at the wet bulb temperature (Pa).
 T_{DB}=Dry bulb temperature (Kelvin).
 T_{WB}=Wet bulb temperature (Kelvin).
 Y=Water-vapor volume concentration.

- (2) The specific humidity on a dry basis of the intake air (H) is defined as: $H=((K_H) (P_v)/(BARO P_v))$
- (3) The partial pressure of water vapor may be determined using a dew point device. In that case: P_v=P_{DP}
- (4) The percent of relative humidity (RH) is defined as: RH= $(P_v/P_{DB})100$

(5) The water-vapor volume concentration on a dry basis of the engine intake air (Y) is defined as: $Y=((H)(M_{air})/(M_{H2O})=P_{\nu}/(BARO\ -\ P_{\nu})$

(d) NO_X correction factor. (1) NO_X emission rates ($M_{NOx \, mode}$) shall be adjusted to account for the effects of humidity and temperature by multiplying each emission rate by K_{NOx} , which is calculated from the following equations:

$$\begin{split} & c_{\text{NNOx}} = (K)(1 + (0.25(\log K)^2)^{1/2}) \\ & K = (K_H)(K_T) \\ & K_H = [C_1 + C_2(\exp((-0.0143)(10.714))] / \\ & [C_1 + C_2(\exp((-0.0143)(1000H))] \\ & C_1 = -8.7 + 164.5 \exp(-0.0218(A/K_T)) \end{split}$$

 $C_2=130.7 + 3941exp(-0.0248(A/F)_{wet})$ Where:

(A/F)_{wet}=Mass of moist air intake divided by mass of fuel intake.

 $K_T=1/[1-0.017(T_{30}-T_A)]$ for tests conducted at ambient temperatures below 30 °C.

 K_T =1.00 for tests conducted at ambient temperatures at or above 30 °C.

 T_{30} =The measured intake manifold air temperature in the locomotive when operated at 30 °C (or 100 °C, where intake manifold air temperature is not available). T_A =The measured intake manifold air

the ambient temperature ($^{\circ}$ C), where intake manifold air temperature is not available).

(e) Other calculations. Calculations other than those specified in this section may be used with the advance approval of the Administrator.

[FR Doc. 01-55530 Filed 11-23-01; 8:45 am]

Editorial Note: On Monday, November 26, 2001, this rule document FR Doc. 01-55530 appeared on 66 FR 58953–58964. Due to additional text being inadvertently added, it is being reprinted in its entirety.

[FR Doc. R1–55530 Filed 11–28–01; 8:45 am] BILLING CODE 1505–01–D

FEDERAL RESERVE SYSTEM

[Docket No. R-1115]

Federal Reserve Bank Services

Correction

In notice document 01–27779 beginning on page 56310 in the issue of Wednesday, November 7, 2001, make the following corrections:

1. On page 56310, in Table 1, the title should have appeared as follows:

temperature in the locomotive as tested (or should ha

TABLE 1.—PRO FORMA COST AND REVENUE PERFORMANCE^a

2. On page 56315, in Table 5, in the fourth column, the column title, "Estimated growth 2001 (percent)"

should read, "Estimated 2001 growth (percent)".

3. On the same page, Table 7 should have appeared as follows:

TABLE 7.—SELECTED CHECK FEES

	2001 Current price ranges	2002 price ranges
Items:	(per item)	(per item)
Forward-processed	,	, ,
City	\$0.001 to 0.079	\$0.001 to 0.079
RCPC	\$0.003 to 0.200	\$0.003 to 0.300
Forward fine-sort		
City	\$0.003 to 0.021	\$0.003 to 0.021
RCPC	\$0.003 to 0.036	\$0.004 to 0.036
Qualified returned checks		
City	\$0.08 to 0.85	\$0.08 to 0.85
RCPC	\$0.10 to 1.15	\$0.10 to 1.15
Raw returned checks		
City	\$1.05 to 5.00	\$1.05 to 5.00
RCPC	\$1.05 to 5.00	\$1.05 to 5.00
Cash letters:	(per cash letter)	(per cash letter)
Forward-processed a	\$2.00 to 32.00	\$2.25 to 36.00
Forward fine-sort	\$3.00 to 14.00	\$3.50 to 14.00
Returned checks: raw/qualified	\$2.00 to 14.00	\$2.00 to 14.50
Payor bank services:	(Fixed) (per item)	(Fixed) (per item)
MICR information	\$2–15 \$0.0020–0.0070	\$2–15 \$0.0030–0.0110
Electronic presentment	\$1–11 \$0.0005–0.0100	\$1 –12 \$0.0005 – 0.0100
Truncation	\$2–7 \$0.0020–0.0180	\$2-7 \$0.0040 -0.0180
Image capture	\$2–15 \$0.0020–0.02	\$2-15 \$0.002-0.02
Image delivery	Varies 5 \$0.001-0.008	I f
Image archive	N/A \$0.001–0.01	N/A \$0.001-0.01
Image retrieval	N/A \$0.3–5	

Note: Bold indicates change from 2001 prices.

^aCash letter fees for forward-processed items transported on Check Relay for 2001 and 2002 include a fifty-cent surcharge due to higher fuel costs.

- ^b Fixed fee varies by media type.
- 4. On page 56319, in Table 10, the line below the title, "In millions of dollars" should read, "[In millions of dollars]".
- 5. On page 56321, in the second column, in the footnote, in the second to the last line, "shore" should read, "short".
- 6. On page 56323, Table 13 should have appeared as follows:

TABLE 13.—COMPARISON OF PRO FORMA BALANCE SHEETS FOR FEDERAL RESERVE PRICED SERVICES
[Millions of dollars—average for year]

	2002	2001
Short-term assets:		
Imputed reserve requirement on clearing balances ²⁷	\$ 678.5	\$ 742.4
Investment in marketable securities ²⁷	5,473.0	6,681.9
Receivables	81.7	77.3
Materials and supplies	3.8	3.6
Prepaid expenses	27.8	23.4
Items in process of collection ²⁸	4,102.8	3,606.7
Total short-term assets	10,367.6	11,135.3
Long-term assets:	,	•
Premises ²⁹	431.1	417.5
Furniture and equipment	177.7	185.5
Leasehold improvements and long-term prepayments	70.4	73.9
Prepaid pension costs	800.1	718.5
Total long-term assets	1,479.3	1,395.4
Total assets	\$11,846.9	\$12,530.7
Short-term liabilities:		
Clearing balances and balances arising from early credit of uncollected items	\$ 7,377.5	\$ 7,424.3
Deferred credit items ²⁸	3,509.8	3,606.7
Short-term debt ³⁰	0.0	18.9
Short-term payables	103.9	85.4
Total short-term liabilities	10,991.2	11,135.3
Long-term liabilities:	000.4	054.0
Postemployment/retirement benefits	263.4	251.9
Long-term debt ³⁰	0.0	479.1
Total long-term liabilities	263.4	731.0
Total liabilities	11,254.6	11,866.3
Equity	592.3	664.4
Total liabilities and equity	\$11,846.9	\$12,530.7

²⁷Funded with clearing balances.

²⁸Represents float costs that are directly estimated at the service level.

²⁹Includes allocations of Board of Governors' assets to priced services of \$1.1 million for 2002 and \$0.7 million for 2001. ³⁰No debt is imputed in 2002 because clearing balances are used as an available funding source.

7. On page 56324, Table 14 should have appeared as follows:

TABLE 14.—PORTION OF CLEARING BALANCES USED TO FUND PRICED SERVICES ASSETS IN 2002

[Dollar amounts in millions]

A. Short-term asset funding: Short-term assets to be funded: Receivables	\$81.7 3.8 27.8		
Total short-term assets to be funded		113.3	
Short-term payables		103.9	
Portion of short-term assets funded with imputed short-term debt or non-core clearing balances ³¹ B. Long-term asset funding: Long-term assets to be funded:			9.4
Premises	\$431.1		
Furniture and equipment Leasehold improvements and long-term prepayments	177.7 70.4		
Prepaid pension cost	800.1		
Total long-term assets to be funded		\$1,479.3	
Postemployment/retirement benefits liability	263.4		
Imputed equity 32	592.3		
		855.7	
Portion of long-term assets funded with imputed long-term debt or core clearing balances 31			623.6
C. Total clearing balances used for funding priced-services assets			\$633.0

³¹Clearing balances shown on table 13 are available for funding priced-services assets. Using these balances reduces the amount available for investment in Treasury bills for the net income on clearing balances calculation. Short-term assets are funded with non-core clearing balances. Long-term assets are funded with core clearing balances; a total of \$4 billion in balances is available for this purpose. No short- or long term dobt is imputed.

long-term debt is imputed.

32 See table 16 for calculation of required imputed equity amount.

- 8. On page 56325, in Table 15, under the Total column, in the first entry, "\$78.5" should read, "\$678.5".
- 9. On the same page, in Table 16, the title should have appeared as follows:

TABLE 16.—DERIVATION OF THE 2002 AND 2001 PSAF

[Dollar amounts in millions]

10. On page 56326, in the continued Table 16, in the first entry, omit "Total equity".

- 11. On the same page, in Table 17, in the Weighted assests column, in the first entry, "0.0" should read, "\$0.0".
- 12. On page 56328, in the "Noncash Collection Fee Schedule—Continued"

table, in the fees column, " $^{52}40.00$ " should read, " $^{40.0052}$ ".

13. On page 56329, the table title should appear as follows:

TEST AND CONTINGENCY OPTIONS⁶¹

[FR Doc. C1–27779 Filed 11–28–01; 8:45 am] BILLING CODE 1505–01–D

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 121

[Docket No. FAA-2001-10770;SFAR 92-2]

RIN 2120-AH54

Flightcrew Compartment Access and Door Designs

Correction

In rule document 01–29280 beginning on page 58650 in the issue of

Wednesday, November 21, 2001, make the following correction:

SFAR 92-2 [Corrected]

On page 58653, in the third column, in paragraph 4, in the 10th line, after "the" should read, "flightcrew compartment shall be available to any crewmember during flight, except for".

[FR Doc. C1–29280 Filed 11–28–01; 8:45 am] $\tt BILLING\ CODE\ 1505–01–D$